

United States Department of the Interior

OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT SUITE 310 625 SILVER AVENUE, S.W. ALBUQUERQUE, NEW MEXICO 87102



In Reply Refer To:

0076

November 27, 1991

Permit: <u>ACT/007/005</u>
Mine Name: <u>Skyline</u>

Tho 5- Reth buy

Mr. Lowell P. Braxton Associate Director, Mining Division of Oil, Gas and Mining 3 Triad Center, Suite 350 355 West North Temple Salt Lake City, UT 84180-1203

_Other (Give explanation).

DEC 0 2 1991

DIVISION OF OIL GAS & MINING

Dear Mr. Braxton:

Federal Ten-Day Notice 91-02-244-9 is being issued for a violation that likely existed at the time of the last State complete inspection (LSCI). Specific details are as follows:

Date of Federal Inspection: 11/15/91; Date of LSCI: 9/25/91

The determination that the State did not cite the violation is based on one or more of the following reasons:

One	or more or the rorrowing reasons:
***************************************	_The condition was identified in a State inspection report but no State enforcement action was taken.
	Design criteria or required certification has not been met for a structure in existence as of the last State complete inspection (sediment pond, excess spoil fill, etc.)
X	Necessary controls that were required at the time of the last State complete inspection have not been established (diversion ditches, sediment ponds, top soil protection, signs and markers, etc.)
	_Site conditions indicate that the violation(s) noted had been in existence at the time of, or prior to, the last State complete inspection.

Mr. Lowell P. Braxton

Indicate below the Division's reason(s) for not citing the alleged violation:
Not a violation
Precluded by State policy
Not included under State program
Warning given in Lieu of a Citation
Violation not recognized (missed)
Practice allowed under approved permit
Too minor to cite
X Working with operator to correct was submitted program ourselvest
Other:
Signature James P Brother Date 12-2-91
Please return your signed and dated response to the Albuquerque Field

Sincerely,

Stephen G. Rathbun, Chief Inspection and Enforcement Branch

Enclosure

This usual was previously inspected y 05 m, and not raised. Based upon the agreement weather with stap during the November 5 th, £ \$ th discussions, 05 m agreed to categorise that as a "nextend miss" and not last in the LSCi category for analongth